

Figure 2. Gross lesions observed on fish collected from the Chesapeake Bay watershed prior to and during fish kills: *(A)* Raised mucoid areas found to be papillomas; *(B)* small raised, reddened areas; *(C)* large red, raised lesions; *(D)* erosions with pale necrotic tissue; *(E)* erosions of skin and muscle; and *(F)* pale areas covered with fungal hyphae (modified from Blazer and others, 2010).